


BEAUFORT COUNTY, SC

FEMA-4286-DR | SC - HURRICANE MATTHEW
ROW COLLECTION

Hazard Removals By Day



Today's Hazard Removals

Total Crews in the Field	1
Hangers	
1A-HANGER REMOVAL PER TREE	49
Leaners	
2B-TREE REMOVAL 13 - 24.99 IN DIAMETER	2
Stumps	

Cumulative Hazard Removal

Progress to Date

	<u>Estimated</u>	<u>Completed</u>	<u>Percent</u>
Hanger	0	61,321	0.0 %
Leaner	0	3,092	0.0 %
Stump	0	124	0.0 %
Total	0	64,537	

Productivity Statistics

Hanger Removal Maximum	2,313
Hanger Removal Average	786
Hanger Removal Minimum	2
Leaner Removal Maximum	136
Leaner Removal Average	47
Leaner Removal Minimum	1
Stump Removal Maximum	64
Stump Removal Average	62
Stump Removal Minimum	61

***All figures are estimates pending reconciliation**